

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	Examiner: Ngan V. Ngo Group Art Unit: 2814
Hidekazu TAKAHASHI)	
Appl. No.: 10/617,668	;	
Filed: July 14, 2003)	
For: SOLID-STATE IMAGING APPARATUS AND CAMERA USING THE SAME APPARATUS	; ;)	
U.S. Patent No.: 6,803,614 B2)	
Issued: October 12, 2004)	November 30, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate
DEC 0 3 2004

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/01/2004 NNGUYEN2 00000023 6803614

01 FC:1811

100.00 DP

DEC 0 6 2004

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Daniel S. Glueck Attorney for Patentee Registration No.: 37,838

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

DSG/dc

DC_MAIN 185704v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 6,803,614 B2

DATED

: October 12, 2004

INVENTOR(S): Hidekazu TAKAHASHI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title Page, At (57) Abstract

Line 6, "An" should read --an--.

In the drawings, Sheet 6:

Figure 6, item 310, "OPERATTION" should read -- OPERATION--.

COLUMN 1:

Line 53, "sown" should read --shown--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>6,803,614 B</u>2

No. of add'l. copies @ 30¢ per page

DEC 0 6 2004



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,803,614 B2

DATED

: October 12, 2004

INVENTOR(S): Hidekazu TAKAHASHI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 12, "a intrinsic" should read -- an intrinsic--.

COLUMN 6:

Line 36, "total-control" should read --total control--.

COLUMN 7:

Line 5, "filer" should read --filter--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

DEC 0 6 2004

PATENT NO. <u>6,803,614 B2</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 6,803,614 B2

DATED

: October 12, 2004

INVENTOR(S) : Hidekazu TAKAHASHI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title Page, At (57) Abstract

Line 6, "An" should read --an--.

In the drawings, Sheet 6:

Figure 6, item 310, "OPERATTION" should read -- OPERATION--.

COLUMN 1:

Line 53, "sown" should read --shown--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>6,803,614 B2</u>

DEC 0 6 2004

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 6,803,614 B2

DATED

: October 12, 2004

INVENTOR(S): Hidekazu TAKAHASHI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 12, "a intrinsic" should read -- an intrinsic--.

COLUMN 6:

Line 36, "total-control" should read --total control--.

COLUMN 7:

Line 5, "filer" should read --filter--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>6,803,614 B2</u>

No. of add'l. copies @ 30¢ per page

. DEC 0 e sody

